

Model:	9000Q
Version:	V1.33
Issue date:	10 th Jan 2025
Type:	Public

New Features

-

Improvement

- Fix an XMOS reset issue which can cause the digital inputs to stop functioning, requiring a standby-cycle.

Additional information

Firmware update instructions.

1. Turn off the power supply to the device (rear panel mains switch)
2. Install the update file on a FAT32 formatted USB drive (maximum 32GB, folder name must be '9000Q' and contents should 9000Q.bin)
3. Insert the USB drive to the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold front panel standby button.
5. Turn on the power supply to the device (rear panel mains switch) while continuing to hold the standby button.
6. Release the standby button and the display will show 'upgrade processing'.
7. Allow the device to apply the software update. This may take a few minutes.
8. When update is complete, the device is ready to use.

Change history

V1.31

Fix DPLL setting change interrupting the audio on other digital sources

V1.29

First release version

All rights reserved ©IAG Group Ltd.

IAG reserves the right to alter the design and specifications without any notice.

Audiolab is a member of the International Audio Group.

www.audiolab.co.uk